


N61331.AR.001615
NSA PANAMA CITY
5090.3a

LETTER DISCUSSING SITE VISIT TO SITE 307 CONDUCTED 27 JULY 1999 CSS PANAMA
CITY FL
9/3/1999
NAVFAC SOUTHERN



DEPARTMENT OF THE NAVY
SOUTHERN DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
P.O. BOX 190010
2155 EAGLE DRIVE
NORTH CHARLESTON, S.C. 29419-9010



Florida Department of Environmental Protection
Attn: Mr. Dave Grabka, Environmental Specialist
Twin Towers Office Building
2600 Blair Stone Road
Tallahassee, FL 32399-2400

0005

**SITE ASSESSMENT REPORT ADDENDUM SITE 307 NAVY COASTAL
SYSTEMS STATION, PANAMA CITY, FL**

Dear Mr. Grabka:

I would like to thank you for taking the time to meet with me on July 27, 1999, to conduct a site visit for Site 307. The review of Site 307 allowed us an opportunity to walk the site and observe the physical constraints present in the study area (i.e., sea wall at Alligator Bayou, concrete surface area, and existing aboveground storage tank), inspect the spacial distribution of monitoring wells and sampling locations, and visually observe the limited area of the site.

As discussed during our meeting, we would like to proceed with the groundwater sampling and the collection of an additional soil sample as outlined in your review letter issued for the Site Assessment Report (SAR) for Site 307. Given the location and spacing of the existing monitoring wells, it is proposed the additional monitoring well requested in the review letter not be installed at this time. The need for the additional monitoring wells will be evaluated and discussed when the results from the second round of groundwater sampling and the soil sample analysis have been reviewed and evaluated.

Please let us know if this course of action is appropriate to address your concerns with the SAR.

Sincerely,

NICK UGOLINI
Remedial Project Manager
UST Program

**SITE ASSESSMENT REPORT ADDENDUM SITE 307 NAVY COASTAL
SYSTEMS STATION, PANAMA CITY, FL**

Copy to:

Mr. A McDonald, CSS

[REDACTED], RINOC